


Acton Survey & Engineering, Inc.

P.O. Box 666, 97 Great Rd. #6 • Acton, MA • 01720

Phone: (978) 263-3666 • Fax: (978) 635-0218

Email: actonsurvey@verizon.net



July 17, 2007

Acton Conservation Commission
472 Main Street
Acton, MA 01720

VIA USPS, FAX & e-mail

Re: Jeanson Homes, Inc.
Lots 2C & 3 Spring Hill Road
DEP # 085-0971

Dear Commission Members:

This letter is in furtherance of the first section of our letter of June 26th pertaining to the status of the streams flowing across and from Lots 2C and 3 Spring Hill Road.

Site observations this morning found both streams flowing across the property and tributary to the fire pond to be dry.

The stream downhill of Springhill Road was found to have isolated pockets of water along less than 10 percent of its length, but water was not flowing.

Precipitation and groundwater levels are reported to be normal.

The streams are therefore intermittent by observation and according to the criteria established by applicable regulations.

Very truly yours,
Mark T. Donohoe, PE

A handwritten signature in black ink, appearing to read "Mark T. Donohoe".

For:
Acton Survey & Engineering, Inc.

cc: Jeanson Homes, Inc.